

**CCR CELL NOS. 3 & 8
ANNUAL INSPECTION
BY
QUALIFIED PROFESSIONAL ENGINEER
AS REQUIRED UNDER OAC 252:517-13-5(b)(1)**

Facility Name:	Big Fork Ranch			
Permit Number:	ODM, LE-1884; ODEQ TO BE ASSIGNED			
Permittee:	Evans & Associates Construction Co., Inc.			
Inspection Period:				
Date of Field Inspection:	9-13-17			
Review Previous Weekly and Annual Inspections	Yes	X	No	

Foundation: (stability, lack of vegetation, removal of topsoil)

	Yes	No	N/A
Foundation appears stable	X		
Any seepage in the area of the foundation or pile		X	
Potential structural weakness		X	

Foundation Comments / Corrective Actions:

NONE

Construction and Stability: (description of material, compaction, lift thickness, slopes, construction methods)

	Yes	No	N/A
Lifts are adequately compacted	X		
Tension cracks noted along surface of pile		X	
Base of pile appears stable	X		
Side slopes of pile appear stable	X		
Any indication of potential failure or instability, slumping or structural weakness		X	

Construction and Stability Comments / Corrective Actions:

NONE

Drainage: All drainage structures appear to be working properly.

	Yes	No	N/A
Drainage around pile is in place and appears adequate	X		
Signs of erosion along ash product pile		X	
Surface of pile is sloped to prevent water ponding	X		

Drainage Comments / Corrective Actions:

NONE

Volume of CCR in the Cells: 74,000 (cu. yd.) on 9-13-17 (date)

Changes in CCR Fill Stability and Geometry Since Last Annual Inspection:

NONE


General Comments:

NONE

Inspected By:

Saeed Zahrai, P. E.

Printed Name


Signature

9-13-17

Date

P. O. Box 2228, Edmond, Ok 73083

Address

405-557-0000

Telephone



Professional Engineer Registration No. 18138

(Seal)